

Jeff's Bus Lane - Vehicle to Service Audit

Arriva Northumbria

28/01/06

Ashington Depot

35	342	416	420	442	A2	M1	M3	X18	X31	X32/X33
281	889	274	282	892	917	914	913	273	7370	7257
290	912		2713	915				283/7410	7375	7373
7254	916			2716					7376	7374
7258									7377	7421
									7411	7423

Alnwick Depot

405/406	420	472	501/505etc	518
908	909	2714	1210	7255
			1211	7371
			1212	7412
			4084	7413
			7251	

Blyth Depot

48	101	308	337	343	344	345	363/364	365	390	391	441
	1728	7436		2654	2669	2657	287		2673	2672	1702
		7437		2662	2671		7389				1802
		7438		2668			7392				1803
		7440					7439				1801/7383
		7441									
		7442									

443	447/448	810/811	C1	C2	W1-4	X1/EX1	X11	X24	X25/26	X44
7250/2659	2646	2652	1717	1733	1774	277	7381/????	279/7256	276	
	2647	2663	1726		1775	285/????	7383/????	7385	????/285	
	2648	2670				7382	7384	7386	????/7381	
	2650						7388	7390		

Hexham Depot

74/75	185	602	685	687	801-804
1790		4524	1202	1716	1732
		4525	1204		1749
		4526	1214		1760
		4527			
		4528			
		4529			

Jesmond Depot

9X	42/43	44	45	306	350	351	355	356	604	M46	M55
922	4506	271	4510	629	1759	1758	4501	621	4516	1703	626
1741	4507	272	4511	7416			4503	4509	4517	1729	1701
	4508	4502	4514	7419			4505	7418	4518		1792
	4520	4515	4523	7432			4512	7420			
	4521			7433							
	4522			7434							

X31	X64
7422	1730
7424	1750
	1751

RED - UNUSUAL WORKING

GREEN - REGULAR WRONG TYPE WORKING

BLUE - DEPOT LOAN