

## Jeff's Bus Lane - Vehicle to Service Audit

**Arriva Northumbria**

**02/02/2008**

**Ashington Depot**

35	340/342	420	518	A2	X18	X31	X32	X33
1923	915	4015	913	2668	274	7412/7258	281	7436
1924	919	7220	1800	2671	290	7413/????	7411/289	7437
4502	2602					7423	7508	7438
4503	2672					7507	7510	7509
	2673					7512	7513	
	2713							
	2716							

**Alnwick Depot**

420	472	501/505etc		518
7374	937	1210	7370	7371
		1211	7372	7373
		1212	7376	7375
				7377

**Hexham Depot**

74/75	601	602	684	685	687	801-804
1759/1792/1760	2623	4525	1790	1202	1760/1792	1732/1792
		4526		1204		1749
		4527		1205		2641
		4528		1214		
		4529				
		4530				

**Jesmond Depot**

40/41/42	44	45	306	355	356	604	M46	M55
4517	4523	4511	7430	4504	7414	4507	1750	1729
4519	7252	4514	7432	4506	7417	4510	1752	1730
4520	7418	4515	7433	4508	7419	4516/????		1731
4521	7421	7431	7434	4513	7420	7416		1758
4522			7435					
			7445					
			7446					

**Blyth Depot**

10/11/12/343/C2	48/447/448	101	308*	337	363	364	390	391
1702	2660	1726	1728	7501	1740	7387	287/????	2649
1721	2661	2646	1733	7502	1741	7440/7385	????/288	7441
1724	2662	2650	2667	7503	1799			
2648	2663	2651		7504				
2657	2664	2652		7505				
2658	2665	2654		7506				
		2655						

\*7439 dia round trip to allow rest to drop back for washing

393	441	C1	W1/W2	W3/W4	X1	X2	X3	X5	X6
2669	1961/7256	2653	1773	1774	285/7389/279	7256/7392/280	279/????	288/287	280/7392
	1962		1775		????/285	7385/7382	????/7389	7385/7439	284
	1963				7250	7387/7381	7388		
	7383				7390	7391	7393/282		

RED - UNUSUAL WORKING

GREEN - REGULAR WRONG TYPE WORKING

BLUE - DEPOT LOAN

X44
2659